



TECHNICAL MEMO

IWSC TECHNICAL MEMO #25-08

To: All IMSA WeatherTech SportsCar Championship LMP2 Participants
 From: IMSA Competition
 Date: February 18, 2025
 Re: Mandatory LMP2 Loom Reliability Update

One Daytona Blvd.
 Daytona Beach, FL 32114
 P: +1 (386) 310-6500



LMP2 Class:

IMSA requires an update to the Oreca LMP2 IMSA Loom Set. **This is a mandatory update which must be performed and installed in the Car prior to Pre-Event Inspection at the 2025 Sebring Race Event.**

All parts of the loom detailed in the image below must be returned to Creative Motorsports Solutions immediately to be inspected and updated in an effort to improve reliability of the timing, driver ID, and leader light systems.

Ship all loom parts including return shipping label to:
Creative Motorsports Solutions USA LLC
 222 Oakridge Blvd.
 STE 120
 Daytona Beach, FL 32118

